

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Thursday, August 2, 2012

Kalamazoo River / Enbridge Spill

## Weather / River Conditions for Thursday, August 2, 2012


Conditions: Sunny

Ambient Air Temperature High: 88° F

Average River Water Temperature: 75.93° F

Average River Sediment Temperature: 75.42° F

### Water and Sediment Temperature



Prepared by:  
Karen Berecz  
START-USEPA  
Situation Unit Leader



1. MP 5.25 to MP 5.60 LDB sheen observed, sheen sweep boat was observed operating in area.



2. MP 5.25 LDB observed sheen and tar globules.



3. MP 5.50 LDB sheen observed.



4. MP 5.63 to control point LDB sheen observed, sheen sweep boat was observed operating in area.



5. MP 5.65 LDB sheen observed.



6. Ceresco Dam sheen and organic matter collecting along the control point.



7. MP 5.50 RDB observed the sweep boat operating.



8. C5 Boat Launch RDB shoreline, no sheen observed.



9. MP 15.5 South Mill Pond, sheen observed from Burnham Street Bridge.



10. MP 15.5 RDB Sheen observed from Burnham Street Bridge.



**11. MP 21.5 RDB Sheen observed from Custer Drive Bridge, sheen sweep boat operating in area.**



**12. MP 23.10 RDB sheen observed, sheen sweep boat operating at location.**



13. MP 23.10 observed sheen sweep boat operating at location.



14. MP 24.75 no sheen observed.



15. MP 26.00 RDB sheen observed, sheen sweep boat not warranted.



16. MP 26.25 RDB sheen observed, no sweep boat warranted.



17. MP 26.25 RDB sheen observed, no sweep boat warranted.



18. MP 26.75 RDB no sheen observed.



**19. MP 27.0 RDB river bank erosion restoration work appears near completion.**




**20. Morrow Lake Delta Gate E North, organic matter collecting along boom.**



21. Morrow Lake Delta Boom C, observed boom maintenance.



22. Morrow Lake South Cove sheen observed, sweep boat operating in area.



23. Sheen and tar globule observed in South Cove on Morrow Lake, sheen sweep boat operating in area.



24. Morrow Lake North Cove sheen observed, sheen sweep boat operating at location.



25. Morrow Lake observed the sweep boat operating in North Cove.



26. Morrow Lake sheen observed, sweep boat not warranted.